

# Product Retirement Notice

PRN # 14-14

May 20, 2014

## End of Life Plan For 8520 & 8820 Industrial Scanners

This notice serves as formal communication of Honeywell Scanning & Mobility's intent to discontinue the following scanning products:

- 8520
- 8820

### Regions Affected:

- Asia Pacific (AP)
- Latin America (LA)
- Europe, Middle East, India, Africa (EMEIA)
- North America (NA)

### Reason for Retirement:

On March 17<sup>th</sup>, 2014, Honeywell launched the Granit 1280i full-range industrial scanner.

The new Granit 1280i...

- **"Goes the distance,"** reading 1D barcodes as far out as 16.5 m (54 ft) or as close as 8.9 cm (3.5 in);
- **"Is built Granit Tough,"** with an IP65 housing and a 6.5-foot drop spec to concrete;
- **"Loves the cold,"** especially with our new industrial-grade cable (optional) capable of withstanding 300,000 90-degree bends at -30° C (-22° F) – making this the ultimate long-range scanner for cold storage environments and a perfect complement to your vehicle-mounted computer sales.

Granit 1280i will be replacing the existing 8520 serial interface model, accounting for most of the sales in this product class. The cordless, KBW, and USB interface models will be replaced by SR61XR scanner.

This retirement notice attempts to identify all SKUs affected by the discontinuation of the 8520 & 8820 family of industrial scanners. It is possible that some part numbers were missed in the list provided. Honeywell reserves the right to include omitted SKUs if they are related to the products listed above, even if the SKU is not specifically listed in this notice. Those omitted SKUs are subject to the terms specified within this document. As outlined below, Honeywell recommends Granit 1280i and SR61XR to replace the 8520 and 8820 series. If you are unsure of a specific SKU, please contact your Honeywell representative for clarification.

Product Name	Part Number	Description
8520	8520326SCANNER	LS3408ER Scanner w/cable, D9
8520	8520333SCANNER	LS3408ER Scanner, no cable
8520	8520331SCANNER	LS3408R Scanner w/cable 9ft, PS2
8520	8520332SCANNER	LS3408ER Scanner w/cable USB Type A connector
8820	8820A327SCNRBTER	LS3578ER Bluetooth Scanner

### Recommended Replacement Products:

Current SKU	Replacement SKU	Description
8520326SCANNER	1280IFR-3SER	Serial Kit: 1D, FR focus, red scanner (1280IFR-3), RS232 black, DB9 Female, 3m coiled cable (CBL-020-300-C00), with vibrator
8520333SCANNER	1280IFR-3	Scanner, 1D, FR focus, red scanner, RS232, with vibrator
8520331SCANNER	SR61TXR-002 236-214-001	SR61TXR Near Far 2D imager (EX25) (EX25c) Cable: PS2 6.5ft straight Y Power by host
8520332SCANNER	SR61TXR-USB001	SR61TXR USB Scanner Kit (includes Scanner & 236-240-001 USB 2 Cable, power from host)
8820A327SCNRBTER	SR61BXR-CB-001	Bluetooth Scanner, Battery, Charge base, PS (SR61B XR Near Far Scanner kit, includes charge base and power supply (order AC line cord separately))

# Product Retirement Notice

---

## Timeline of Events:

<b>Last Time Buy (Scanner, Kits and Service Plans)</b>	Honeywell will not accept scanner, kits or service contract orders after this date	15-Aug-14
<b>Last Time Buy (Accessories)</b>	Honeywell will not accept accessory hardware orders after this date	15-Aug-17
<b>Last Time Ship (Scanner &amp; Kits)</b>	Honeywell will not ship scanner or kits after this date	15- Nov-14
<b>Last Time Ship (Accessories)</b>	Honeywell will not ship accessories after this date	15- Nov-17
<b>Stock Rotation Request</b>	Honeywell will not accept requests for stock rotation after this date	15-Jun-14
<b>Stock Rotation Return</b>	Honeywell must receive all final stock rotated units by this date	30-Jun-14
<b>End of Service</b>	Honeywell will not offer spare parts or servicing of units after this date	15-Nov-19

## Service and Warranty:

Honeywell will maintain our commitment to our customers by supporting and servicing discontinued product at all worldwide service centers throughout the life of all warranties in place, as long as the required parts are commercially available.

## Contact:

Honeywell Scanning & Mobility is committed to providing you with a superior level of customer service. Please contact your Honeywell representative for additional information regarding this communication.

### **For more information:**

[www.honeywellaidc.com](http://www.honeywellaidc.com)

### **Honeywell Scanning & Mobility**

9680 Old Bailes Road

Fort Mill, SC 29707

800.582.4263

[www.honeywell.com](http://www.honeywell.com)

